

## 8L90 IMPROVEMENTS

- UPDATED GM HARNESS-BOTH SIDES
- UPDATED SHIFT ENHANCEMENTS
- UPDATED PULSE DAMPERS
- UPDATED TCC LOCKUP STRATEGY
- CORRECTED-VERIFIED PUMP FUNCTION