

4L60E IMPROVEMENTS

- CORRECTED PUMP/STATOR FOR PROPER HYDRAULIC FUNCTION
- UPDATED PISTONS IN INPUT DRUM ASSEMBLY
- UPDATED BAND FOR PROPER ENGAGEMENT
- VERIFIED PROPER UPDATED SPRAG FOR LONGEVITY
- VALVE BODY UPDATES FOR SHIFT QUALITY
- VALVE BODY TESTED-VERIFIED ON VBT 8000 DYNO