

ALLISON 1000 5 SPEED IMPROVEMENTS

- UPDATED C1 PACK
- UPDATED C3 PACK
- UPDATED C3/C4 PISTON/RETURN SPRINGS
- PUMP UPDATE FOR C1 CLUTCH STABILITY
- PTO COVERS WITH ADDED C3 OILING
- VALVE BODY UPDATED FOR HYDRAULIC AND SHIFT STABILITY
- PUMP AND STATOR BUSHING REPLACED
- VALVE BODY TESTED AND VERIFIED ON VBT 8000 DYNO