

## ALLISON 1000 6 SPEED IMPROVEMENTS

- UPDATED C3 PACK
- PTO COVERS WITH ADDED C3 OILING
- VALVE BODY UPDATED FOR HYDRAULIC AND SHIFT STABILITY
- PUMP AND STATOR BUSHING REPLACED
- VALVE BODY TESTED AND VERIFIED ON VBT 8000 DYNO